


DECT base & Headset repair operation .

Step01: first of all ,make sure headset turn on status (Press mul-function buttom 2second



Base pair mode manual


Step02: Pull out of base power charge (cut off the base power charge adapter) .

Step03: First of all,Consistently press Mic+ button ,Second of all , reconnect with power charge adapter, thridly, the batter light  flash three times and finally loosen Mic+

Step04: Base will enter paired  search mode


Step05: Headset pair mode manual

Pls press mute function  ,See battery light

indicator light on  . that mean pair sucessful


This is photo instruction :

Step 01 :




Headset state	LED Indicator
Power on	Light hold for 2S

Step02,03 :



Step05:



How to testing base& headset repair sucessufly ,only press Mul-function button headsets and

base will be show pair sign



Link between headset and base